



SolaMesh® Care and Maintenance Instructions

High Density Polyethylene (HDPE) is used in the manufacturing of SolaMesh. HDPE is very stable when exposed to UV rays but can become dirty over time. SolaMesh can be cleaned but must be done using a cleaning agent that will not harm HDPE.

Please do not use cleaning products containing the chemicals listed below as they may affect the life of your product and warranty. Please be sure to carefully read ingredients listed on the cleaner label or found on their SDS (MSDS) sheets, available from the manufacturer.

Harmful cleaning products contain:

Bleach	Halogens	Solvents
Acids	Sulfur	Strong Alkaline

Mild cleaning products such as dishwashing soaps can be used. Mix the preferred cleaning agent with water and use a soft bristle brush to clean the desired area. Rinse with cold to warm (less than 120F) water. Thoroughly rinse the fabric using normal water pressure. Using a pressure washer to clean the fabric may cause damage.